

इंटरनेट

मानक

Disclosure to Promote the Right To Information

Whereas the Parliament of India has set out to provide a practical regime of right to information for citizens to secure access to information under the control of public authorities, in order to promote transparency and accountability in the working of every public authority, and whereas the attached publication of the Bureau of Indian Standards is of particular interest to the public, particularly disadvantaged communities and those engaged in the pursuit of education and knowledge, the attached public safety standard is made available to promote the timely dissemination of this information in an accurate manner to the public.

“जानने का अधिकार, जीने का अधिकार”

Mazdoor Kisan Shakti Sangathan

“The Right to Information, The Right to Live”

“पुराने को छोड़ नये के तरफ”

Jawaharlal Nehru

“Step Out From the Old to the New”

IS 3455 (1971): Gauging practice for plain work pieces [PGD
25: Engineering Metrology]



“ज्ञान से एक नये भारत का निर्माण”

Satyanarayan Gangaram Pitroda

“Invent a New India Using Knowledge”



“ज्ञान एक ऐसा खजाना है जो कभी चुराया नहीं जा सकता है”

Bhartrhari—Nitiśatakam

“Knowledge is such a treasure which cannot be stolen”

BLANK PAGE



*Indian Standard***GAUGING PRACTICE FOR PLAIN
WORKPIECES***(First Revision)*

1. Scope — Lays down the gauging practice for inspection of plain workpieces with dimensions less than 500 mm. This standard also gives the manufacturing tolerances and the permissible wear limit of the gauges.

2. Inspection Gauging of Plain Workpieces

2.1 Unless specified to the contrary, inspection by limit gauges is recognized as the acceptable method for dimensional conformity to the specification of plain workpieces. To avoid any dispute requiring checking of the conformity of the gauges of the manufacturer, the following procedure is recommended in the use of gauges of the manufacturer and of the purchaser.

2.2 Inspection by the Manufacturer — Generally the inspection department that checks the workpieces made in the workshop may use the same types of gauges as those used in the workshop. In order to avoid differences between the results obtained by the workshop and inspection department it is recommended that the workshop uses new or only slightly worn gauges whilst the inspection department uses gauges having sizes nearer the permissible wear limit.

2.3 Inspection by the Purchaser — There are three possible procedures for inspection on behalf of the purchaser by an inspector who does not belong to the manufacturing plant concerned:

- a) the inspector may gauge the workpieces with the manufacturer's own gauges, providing he first checks the accuracy of these gauges;
- b) the inspector may use his own gauges, made in accordance with this standard, for inspecting workpieces. It is recommended that these gauges should have sizes near the wear limit in order to avoid differences between the results obtained by the manufacturer and the inspector;
- c) the inspector may use his own inspection gauges for checking the workpieces. The disposition of the tolerance zones for these gauges should be such as to ensure that the inspector does not reject workpieces the sizes of which are within the specified limits.

3. Reference Temperature

3.1 The standard reference temperature for all industrial length measurements shall be 20°C. This is also the temperature at which dimensions specified for workpieces and the inspection instruments are defined and at which the inspection should normally be carried out.

3.2 If the workpieces and the gauges have the same coefficient of linear expansion (for example, steel workpieces and steel gauges), the checking temperature may deviate from 20°C without detriment to the result, provided that the temperatures of both gauges and workpieces are the same.

3.3 If the workpieces and gauges have different coefficients of linear expansion (for example, steel workpieces and carbide gauges or brass workpieces and gauges of steel or carbide), the temperatures of both should be close to 20°C at the time of gauging.

4. Limits of Size for Gauging (Taylor Principle)

4.1 In order to ensure, as far as is practicable, that the functional requirements of the limits of sizes as given in IS : 919-1963 ' Recommendations for limits and fits for engineering (revised) ' are attained, the limits of size should be interpreted in the following way within the basic dimensions:

- a) For holes, the diameter of the largest perfect imaginary cylinder which can be inscribed within the hole so that it just contacts the highest points of the surface, should not be a diameter smaller than the GO limit of size. In addition, the maximum diameter at any position in the hole shall not exceed the NO GO limit of size.
- b) For shafts, the diameter of the smallest perfect imaginary cylinder which can be circumscribed about the shaft so that it just contacts the highest points of the surface, should not be a diameter larger than the GO limit of size. In addition, the minimum diameter at any position on the shaft shall not be less than the NO GO limit of size.

Adopted 20 September 1971

© April 1993, BIS

Gr 8

4.1.1 The above interpretation means that if the size of the hole or shaft is everywhere at its GO limit then the hole or shaft shall be perfectly round and straight.

4.2 Subject to the above requirements, departures from true roundness and straightness may reach the full value of the diametral tolerance specified. Typical extreme errors of form permitted by this interpretation are illustrated in Fig. 1 and 2. Such extreme errors are unlikely to arise in practice.

Note—The above interpretation of the size limits results from the so-called Taylor principle, called after the name of the late W. Taylor who first laid it down in 1905. It is based on the use of a correct system of limit gauges to inspect shafts and holes. According to this principle a hole should completely assemble with a GO cylindrical plug gauge, made to the specified GO limit of the hole, having a length at least equal to the length of engagement of the hole and shaft. In addition, the hole is measured or gauged to check that its maximum diameter is not larger than the NO GO limit.

4.2.1 The shaft should assemble completely with a ring gauge made to the specified GO limit of the shaft and of a length at least equal to that of the length of engagement of the shaft and hole. Finally the shaft is measured or gauged to check that its minimum diameter is not smaller than the NO GO limit.

4.2.2 In special cases the maximum errors of form permitted by the above interpretation may be too large to allow satisfactory functioning of the assembled parts; in such cases separate tolerances should be given for the form, for example, separate tolerances on circularity or straightness.




FIG. 1 EXTREME ERRORS OF FORM OF HOLE ALLOWED BY THE RECOMMENDED INTERPRETATION OF THE LIMITS OF SIZE

5. Application of the Taylor Principle— Except for allowable deviations (see 6) strict application of the Taylor principle leads to using:

- a plug gauge or a ring gauge having exactly the GO limit diameter and a length equal to the workpiece length (or the engagement length of the fit to be made) for checking the GO limit of the workpiece; and
- a gauge contacting the workpiece surface only in two diametrically opposite points and having exactly the NO GO limit diameter for checking the NO GO limit.

5.1 The GO gauge should perfectly assemble with the workpiece to be inspected and the NO GO gauge should not be able to pass over or in the workpiece in any consecutive position in the various diametrical directions on the workpiece length. (In order that the GO and NO GO limits should not be trespassed, manufacturing and wear tolerances should be taken within these limits.)

6. Allowable Deviation from the Taylor Principle— As the application of the Taylor principle is not always strictly compulsory or comes up against difficulties in conveniently using gauges, certain deviations may be allowed (see 7.9).




FIG. 2 EXTREME ERRORS OF FORM OF SHAFT ALLOWED BY THE RECOMMENDED INTERPRETATION OF THE LIMITS OF SIZE

6.1 At the GO limit a full form gauge is not always necessary or used. For instance:

- The length of a GO cylindrical plug or ring gauge may be less than the length of engagement of the mating workpieces if it is known or assumed that with the manufacturing process used the error of straightness of the hole or shaft is so small that it does not affect the character of fit of the assembled workpieces. This deviation from the ideal facilitates the use of standard gauge blanks.
- For gauging a large hole a GO cylindrical plug gauge may be too heavy for convenient use, and it is permissible to use a segmental cylindrical bar or spherical gauge if it is known or assumed that with the manufacturing process used the error of roundness of the hole is so small that it does not affect the character of fit of the assembled workpieces.
- A GO cylindrical ring gauge is often inconvenient for gauging shafts and may be replaced by a gap gauge if it is known or assumed that with the manufacturing process used the errors of roundness (especially lobing) and straightness of the shaft are so small that they do not affect the character of fit of the assembled workpieces. The straightness of long shafts, which have a small diameter, should be checked separately.

6.2 At the NO GO limit a two-point checking device is not always necessary or used. For instance:

- Point contacts are subject to rapid wear, and in most cases may be replaced where appropriate by small plane, cylindrical or spherical surfaces.
- For gauging very small holes a two-point checking device is difficult to design and manufacture. NO GO plug gauges of full cylindrical form have to be used but the user must be aware that there is a possibility of accepting workpieces having diameters outside the NO GO limit.
- Non-rigid workpieces may be deformed to an oval by a two-point mechanical contact device operating under a finite contact force. If it is not possible to reduce the contact force to almost zero, for example, by using a direct jet pneumatic device, then it is necessary to use NO GO ring or plug gauges of full cylindrical form.

6.3 Some thin-walled workpieces may be out of round (due to internal stresses or heat treatment). In these cases the NO GO limit has the meaning that the circumference of the cylinder corresponding to that limit shall not be transgressed. Therefore NO GO gauges of full cylindrical form have to be applied with a force that just suffices to convert the elastic deformation into circularity but does not expand or compress the wall of the workpiece.

6.4 Lastly, it is not possible to make the gauges exactly to the appropriate workpiece limit; they require to be made to specified tolerances.

7. Limit Gauges

7.0 Limit gauges are used to inspect the workpieces. For gauging internal diameters, they are of the following types:

- a) Full form cylindrical plug gauge,
- b) Full form spherical plug or disk gauge,
- c) Segmental cylindrical bar gauge,
- d) Segmental spherical plug gauge,
- e) Segmental cylindrical bar gauge with reduced measuring faces, and
- f) Rod gauge with spherical ends.

7.0.1 For gauging external diameters, they are of the following types:

- a) Full form cylindrical ring gauge, and
- b) Gap gauge.

7.0.2 To inspect or adjust limit gauges, the following gauges may be used:

- a) *Reference gauges* are either reference disks intended for setting gap gauges, or cylindrical ring or plug gauges used for calibrating gauges or indicating measuring instruments.
- b) *Block gauges* are standards of length having parallel plane end surfaces which are used for calibrating gauges of indicating measuring instruments.

7.1 A *full form cylindrical plug gauge* (Fig. 3A) has a gauging surface in the form of an external cylinder. The method of attaching the gauge to the handle should not affect the size and form of the gauge by producing an undesirable stress.

7.1.1 A small circumferential groove near the leading end of the gauge and a slight reduction in diameter of the remaining short cylindrical surface at the end are recommended to serve as a pilot to facilitate the insertion of the gauge into the workpiece hole.

7.2 A *full form spherical plug or disk gauge* (Fig. 3B) has a gauging surface in the form of a sphere from which two equal segments are cut off by planes normal to the axis of the handle.

7.3 A *segmental cylindrical bar gauge* (Fig. 3C) has a gauging surface in the form of an external cylinder from which two axial segments are either received [Fig. 3C (i)] or removed [Fig. 3C (ii)]. This gauge may have reduced measuring faces (Fig. 3E).

7.4 A *segmental spherical plug gauge* (Fig. 3D) is similar to Fig. 3B but has two equal segments cut off by planes parallel to the axis of the handle in addition to the segments cut off by planes normal to the axis of the handle.

7.5 A *segmental cylindrical bar gauge with reduced measuring faces* (Fig. 3E) is similar to Fig. 3C but has reduced measuring faces in a plane parallel to the axis of the handle.

7.6 A *rod gauge with spherical ends* (Fig. 3F) has spherical end surfaces which form part of one single sphere.

7.7 A *full form cylindrical ring gauge* (Fig. 4A) has a gauging surface in the form of an internal cylinder. The wall of the ring gauge shall be thick enough to avoid deformation under normal conditions of use.

7.8 A gap gauge (Fig. 4B) has for its working size flat and parallel gauging surfaces, or alternatively and preferably has one flat and one cylindrical surface, or two cylindrical surfaces, the axes of these cylindrical surfaces being parallel to the axis of the shaft being checked. The GO and NO GO gaps may lie on the same side of the gap gauge. The gap gauge may be fixed or adjustable.




FIG. 3 RECOMMENDED TYPES OF GAUGES FOR HOLES AND THEIR CORRESPONDING SYMBOLS FOR FIG. 5




FIG. 4 RECOMMENDED TYPES OF GAUGES FOR SHAFTS AND THEIR CORRESPONDING SYMBOLS FOR FIG. 6

7.9 The various types of gauges explained above are illustrated in Fig. 3 and 4. The recommended types of gauges for the different ranges of nominal size of the workpieces are shown in Fig. 5 and 6. The keys to the symbols used in Fig. 5 and 6 are given in Fig. 3 and 4.

WORKPIECE	GAUGES	ORDER OF PREFERENCE	DIAMETER IN mm					
			0	6	10	- 120	315	500
RIGID PARTS	GO	1	Taylor Gauge (square block) with a hole, used for checking hole diameter.					
		2	Taylor Gauge (square block) with a hole, used for checking hole diameter.					
	NOT GO	1	Taylor Gauge (square block) with a hole, used for checking hole diameter.					
		2	Taylor Gauge (square block) with a hole, used for checking hole diameter.					
NON-RIGID PARTS	GO	1	Taylor Gauge (square block) with a hole, used for checking hole diameter.					
		2	Taylor Gauge (square block) with a hole, used for checking hole diameter.					
	NOT GO	1	Taylor Gauge (square block) with a hole, used for checking hole diameter.					

FIG. 5 TYPES OF GAUGES USED TO CHECK HOLES, IN ORDER OF PREFERENCE

WORKPIECE	GAUGES	ORDER OF PREFERENCE	DIAMETER IN mm	
			0	315
RIGID PARTS	GO	1	Taylor Gauge (cylinder) with a hole, used for checking shaft diameter.	
		2	Taylor Gauge (cylinder) with a hole, used for checking shaft diameter.	
	NOT GO	1	Taylor Gauge (cylinder) with a hole, used for checking shaft diameter.	
NON-RIGID PARTS	GO	1	Taylor Gauge (cylinder) with a hole, used for checking shaft diameter.	
	NOT GO	1	Taylor Gauge (cylinder) with a hole, used for checking shaft diameter.	

FIG. 6 TYPES OF GAUGES USED TO CHECK SHAFTS, IN ORDER OF PREFERENCE

8. Inspection of Gauge Sizes

8.1 Reference Gauges—The gauge diameter should be measured between a plane and a spherically-ended anvil having a minimum radius of 10 mm. The value obtained should be corrected for deformation of the surfaces in contact caused by the measuring force, that is, the diameter of the gauge is the diameter when the measuring force is zero. The diameter should be measured in at least four positions selected to reveal form errors.

8.1.1 All the measured diameters of the gauge should be on or between the specified limits of size, and the range, that is, the difference between the maximum and minimum values, should not exceed the form tolerance of the gauge (see 10.2.3). If the presence of lobing is suspected then it may be checked by a three-point measurement or by a roundness measurement.

8.2 Spherical Plug, Disk and Rod Gauges — The diameter of the spherical part of the gauge should be measured between two parallel planes; these planes need only have a small area, for example, the diameter of the plane-ended surface of the anvil of a measuring instrument may only be 5 mm.

8.2.1 The value obtained should be corrected for deformation of the surfaces in contact caused by the measuring force, that is, diameter of the gauge is the diameter when the measuring force is zero.

8.2.2 The diameter should be measured in at least four positions, selected to reveal form errors. All the measured diameters of the gauge should be on or between the specified limits of size, and the range, that is, the difference between the maximum and minimum values, should not exceed the form tolerance of the gauge (see 10.2.3). If the presence of lobing is suspected then it may be checked by a three-point measurement or by a roundness measurement.

8.3 Cylindrical Ring Gauges — The diameter is measured by means of two spherically-ended anvils positioned in a plane normal to the axis of the ring gauge. When moving the measuring instrument in this plane the greatest distance apart of the two anvils determines the diameter. The value obtained should be corrected for deformation of the surfaces in contact caused by the measuring force, that is, the diameter of the gauge is the diameter when the measuring force is zero.

8.3.1 The diameter should be measured in at least four positions, selected to reveal form errors. All the measured diameters of the gauge should be on or between the specified limits of size, and the range, that is, the difference between the maximum and minimum values, should not exceed the form tolerance of the gauge (see 10.2.3). If the presence of lobing is suspected then it may be checked by a three-point measurement or by a roundness measurement.

8.4 Gap Gauges

8.4.1 The *actual size* of a gap is defined as the perpendicular distance between the gauging surfaces, when no force is exerted on the gauge.

8.4.2 The *working size* of a gap gauge is defined as the diameter of a reference disk over which the gap gauge just passes in a vertical direction under the working load marked on it, or, if this is not indicated, under its own weight. Beforehand, the disk should be greased with a thin film of petroleum jelly and then carefully wiped but not rubbed. The gauging surfaces of the gap gauge should be cleaned. The gap gauge should slide over the disk after having been brought carefully to rest in contact with the disk and then released; inertia forces are so avoided.

8.4.3 For heavier gap gauges it is recommended that the working load should be less than the weight of the gauge, so that the working size may be determined more accurately. The positions of the places where the forces counterbalancing part of the weight of the gauge are to be applied (see Fig. 7) should be marked on gauges of nominal sizes above 100 mm.




FIG. 7 LOCATION OF POINTS WHERE FORCES COUNTERBALANCING PART OF WEIGHT OF GAUGE SHOULD BE APPLIED

8.4.4 The working size of a gap gauge is not defined with a zero measuring force, as for the other definitions, because the size of a reference disk is defined with a zero measuring force and the gap gauge may be regarded as a comparator which is intended to transfer (on the particular limit) the size of the reference disk to the workpiece.

8.4.5 In practice a reference disk may be used directly to accept a gap gauge in the case where the disk and the gap gauge are supplied together and the gap gauge has been adjusted to the disk. In other cases the following two alternative procedures are recommended:

- a) The successive loads under which the gap gauge will pass over two reference disks of different diameter are determined under the conditions specified in the definition of the working size. The difference in these two loads is taken as a basis for calculating the working size of the gap gauge at its working load.

- b) A reference disk is taken with a diameter smaller* than the smallest permissible size of the gap gauge. Gauge blocks are wrung successively on the gauging surfaces of the gap gauge, if possible equally distributed so that in one case the sum of the diameter of the reference disk and the gauge blocks is equal to the lowest permissible working size and in the other case to the highest permissible working size of the gap gauge†.

In the first case the gap gauge should pass over the reference disk, and in the second case it should not pass over the reference disk, under the conditions specified in the definition of the working size.

Doubtful cases are decided according to method (b) above.

8.4.6 When the gap gauge is used in a horizontal position, with the axis of the workpiece vertical, its working size is defined as the largest size of a reference disk or gauge block combination over which it can just be moved by hand without excessive force.

8.4.7 The difference between the working size and the actual size of a gap gauge is equal to the amount by which the gauge is deformed by the force applied when determining the working size. The design of the gap gauge should be as rigid as possible in relation to the weight of the gauge so as to keep this difference in size to a minimum.

9. Method of Use of Gauges — The following recommendations relate to the general use of the gauges in the workshop as well as in inspection.

9.1 Gauges for Holes

GO Gauge — A GO gauge should assemble completely with the hole when applied by hand without using excessive force, and the total length of the hole should be checked. When gauging non-rigid workpieces, such as thin-walled parts, the application of too great a force will enlarge the diameter of the hole. A GO segmental gauge should be applied to the hole in at least two axial planes uniformly placed around the circumference.

NO GO Gauge — A cylindrical NO GO plug gauge should not enter the hole when applied by hand without using excessive force. The hole should be checked from both ends, if possible.

A NO GO gauge with spherical measuring surfaces is entered into the hole by tilting it. When it is erected in the hole, contacting the hole on a diameter, it should not be possible to pass it through the hole by hand without using excessive force. This test should be performed at not less than four positions around and along the cylindrical surface of the hole.

9.2 Gauges for Shafts

GO Gauge — The GO gap gauge should pass over a shaft, the axis of which is horizontal, under its own weight or the force marked on the gauge, under the conditions specified in **8.4**.

The GO gap gauge should pass over a shaft, the axis of which is vertical, when applied by hand without using excessive force. It is recommended that the corresponding reference disk should be used to assess the measuring force.

The above test should be applied at not less than four positions around and along the shaft.

A cylindrical GO ring gauge should pass over the complete length of the shaft when applied by hand without using excessive force.

NO GO Gauge — The NO GO gauge should not pass over a shaft, the axis of which is horizontal, under its own weight or the force marked on the gauge, under the conditions specified in **8.4**.

The NO GO gap gauge should not pass over a shaft the axis of which is vertical, when applied by hand without using excessive force.

The above test should be applied at not less than four positions around and along the shaft.

*For gap gauges up to 100 mm it is advisable to make the diameter of the disk 5 mm smaller than the nominal size, and for gap gauges over 100 mm, 10 mm smaller than the nominal size.

†Reference disks made to the lowest and highest permissible sizes may also be used.

10. Manufacturing Tolerances and Permissible Wear of Gauges

10.1 *Symbols* — The following symbols are used in this standard:

D = nominal diameter of workpiece in millimetres;

H = tolerance on cylindrical plug or cylindrical bar gauges;

H_s = tolerance on spherical gauges;

H_1 = tolerance on gauges for shafts;

H_p = tolerance on reference disks for gap gauges;

y = margin, outside the GO workpiece limit, of the wear limit of gauges for holes;

y_1 = margin, outside the GO workpiece limit, of the wear limit of gauges for shafts;

z = distance between centre of tolerance zone of new GO gauges for holes and GO workpiece limit;

z_1 = distance between centre of tolerance zone of new GO gauges for shafts and GO workpiece limit;

α = safety zone provided for compensating measuring uncertainties of gauges for holes of nominal diameter over 180 mm;

α_1 = safety zone provided for compensating measuring uncertainties of gauges for shafts of nominal diameter over 180 mm; and

y' and y'_1 = difference in absolute value between y and α or y_1 and α_1 .

10.2 Limit Gauges

10.2.1 Positions of tolerance zones and wear limits in relation to *workpiece limits* (shown diagrammatically in Fig. 9).

NO GO limit of workpieces — The tolerance zone of new NO GO gauges for nominal sizes up to and including 180 mm is symmetrical to the NO GO limit. For sizes above 180 mm the tolerance zone is symmetrical to a line lying inside the workpiece tolerance zone at a distance α or α_1 from the NO GO limit.

GO limit of workpieces — A reasonable life for GO gauges is provided in two ways:

- the tolerance zone of a new GO gauge is moved inside the workpiece tolerance by an amount z or z_1 ;
- the GO gauge is allowed to wear outside the GO limit of the workpiece by an amount y or y_1 when this value is not zero.

In the range of sizes above 180 mm nominal diameter the values of y and y_1 are reduced by the amount of the safety zones α and α_1 respectively so that in these cases, the actual wear of the GO gauges is limited to y' and y'_1 respectively outside the GO limit of the workpiece (or to α and α_1 within this limit if y and y' are equal to zero).

The values of the y or y_1 margin have been taken as small as possible in order to reduce to a minimum the risk that workpieces with sizes outside the prescribed GO limit be accepted. This margin is therefore provided only in the case of smaller tolerances on workpieces, from IT6 to IT8, the deletion of this margin being possibly contemplated in the future (in connection with the development of low cost low wear gauges).

In the range of sizes above 180 mm nominal diameter the workpiece tolerance has been reduced, at the GO (with y or y_1 margin) and NO GO limits, by the amount of the safety zones α and α_1 . Manufacturers and purchasers should not forget that due to errors of measurement the sizes of workpieces may fall outside the limits of the gauges by the amount of the safety zones α and α_1 and that the extreme workpiece limits, given by y and y_1 , may be reached.

10.2.2 *Tolerances on size of working gauges* — The tolerances on size of working gauges are based on the fundamental tolerances of grades IT1 to IT7 and are shown in Table 1.

Values of α , y , z , etc, for the gauges are shown in Table 2.

Gauge size for component tolerance ' T ', not included in Table 2 shall be calculated by using the data for the next higher values of ' T ' in the same range.

10.2.3 Tolerances on form of working gauges — The tolerances on form of working gauges are based on the fundamental tolerances of grades IT0 to IT5 and are shown in Table 1.

10.3 Reference Disks for Gap Gauges

10.3.1 Positions of tolerance zones with respect to the workpiece limits (shown diagrammatically in Fig. 9).

NO GO limit of workpiece — For nominal sizes up to and including 180 mm the tolerance zone of the reference disk is symmetrical to the NO GO limit. For sizes above 180 mm the tolerance zone is symmetrical to a line lying inside the workpiece tolerance zone at a distance α from the NO GO limit.

GO limit of workpiece — The tolerance zone of the reference disk for a new gap gauge is symmetrical to the z_1 value.

The tolerance zone of the reference disk for checking wear is located in the following manner:

- a) *Workpieces of nominal sizes up to and including 180 mm* — For tolerance grades IT6 to IT8 the tolerance zone of the reference disk is symmetrical to the y_1 value. For tolerance grades IT9 to IT16, y_1 is zero and hence the tolerance zone of the reference disk is symmetrical to the GO limit of the workpiece.
- b) *Workpieces of nominal sizes above 180 mm* — For tolerance grades IT6 to IT8 the tolerance zone of the reference disk is symmetrical to the y'_1 value ($y'_1 = y_1 - \alpha_1$). For tolerance grades IT9 to IT16 y_1 is zero and hence the tolerance zone of the reference disk is symmetrical to the value inside the GO limit of the workpiece.

10.3.2 Tolerances on size of reference disks — The tolerances on size of the reference disks are based on the fundamental tolerances of grades IT1 to IT3 and are shown in Table 1.


Values of α_1, y_1, z_1 , etc, for the reference disks are given in Table 3.

Gauge size for component tolerance ' T ', not included in Table 3 shall be calculated by using the data for the next higher values of ' T ' in the same range.

10.3.3 Tolerances on form of reference disks — The tolerances on form of the reference disks are based on the fundamental tolerances of grades IT1 to IT2 and are shown in Table 1.

10.3.4 Relation between tolerances of gap gauges and their reference disks — The relation between the tolerances H_1 of the gap gauge and the tolerance of its reference disk H_p is as follows:

H^1 determines the limits of size of the working size (see clause 8.4) of a gap gauge. The difference between the limits of size given by H_1 for the gap gauge and by H_p for the reference disk represents a safety zone on both sides of H_p to compensate for errors of measurement, in the same way as α and α_1 do for workpieces of diameters over 180 mm. H_1 and H_p are, therefore, symmetrical (see Fig. 8). Therefore, if according to the definition of working size, gap gauges lie outside the zone H^p but within the zone H_1 , they are still to be regarded as correct.



- H_1 = manufacturing tolerance of the gap-gauge
- H_p = manufacturing tolerance of the reference disk
- A = safety zone

FIG. 8 RELATION BETWEEN MANUFACTURING TOLERANCES OF GAP GAUGES AND OF REFERENCE GAUGES

10.4 Reference Ring and Plug Gauges for Setting Measuring Instruments—The gauges should be made to tolerances on size and form equal to those for reference disks. The tolerance on size is disposed bilaterally with respect to the appropriate test limit of the workpiece. The size of each gauge should be measured across a diameter halfway through the gauge, and the axial plane in which this diameter occurs and the measured size of the gauge should be marked on the end face of the gauge.

11. Formulae for Calculation of Gauge Dimensions

11.1 From the position of the tolerance zones and wear limits in relation to workpiece limits illustrated in Fig. 9, the formulae for calculation of gauge limits can be computed and these are given below. In these formulae, in addition to the symbols given in 10.1, the following are used:

G = higher limit for workpiece, and

K = lower limit for workpiece.

FORMULAE FOR GAUGE DIMENSIONS									
Gauges for	Gauge Size	Nominal Size							
		Up to 180 mm				Above 180 mm			
		Gauges		Reference Gauge		Gauges		Reference Gauge	
		Basic Size	Mfg Tol	Basic Size	Mfg Tol	Basic Size	Mfg Tol	Basic Size	Mfg Tol
Inside measurements	No Go	G	$\pm \frac{H}{2}$ or $\pm \frac{H_s}{2}$	Not Provided		$G - \alpha$	$\pm \frac{H_s}{2}$ or $\pm \frac{H^*}{2}$	Not Provided	
	Go (New)	$K + z$	$\pm \frac{H}{2}$			$K + z$	$\pm \frac{H}{2}$ or $\pm \frac{H_s}{2}$		
	Wear Limit	$K - y$	—			$K - y + \alpha$	—		
Outside measurements	Wear Limit	$G + y_1$	—	$G + y_1$	$\pm \frac{H_p}{2}$	$G + y_1 - \alpha_1$	—	$G + y_1 - \alpha$	$\pm \frac{H_p}{2}$
	Go (New)	$G - z_1$	$\pm \frac{H_1}{2}$	$G - z_1$	$\pm \frac{H_p}{2}$	$G - z_1$	$\pm \frac{H_1}{2}$	$G - z_1$	$\pm \frac{H_p}{2}$
	No Go	K	$\pm \frac{H_1}{2}$	K	$\pm \frac{H_p}{2}$	$K + \alpha_1$	$\pm \frac{H_1}{2}$	$K + \alpha_1$	$\pm \frac{H_p}{2}$

$\frac{*H}{2}$ should only be used when spherical gauges are not used.

11.2 Sample Calculation — Illustrative examples for the calculation of gauge limits are given below:

Required Gauge Size for 25C9 Plug Gauge

The component tolerances will be $\left. \begin{array}{l} + 0.162 \\ + 0.110 \end{array} \right\}$ According to IS : 919-1963

Corresponding work limits will be $G = 25.000 + 0.162 = 25.162$ mm
 $K = 25.000 + 0.110 = 25.110$ mm




FIG. 9 TOLERANCE ZONES OF LIMIT GAUGES AND REFERENCE DISKS

For plug gauges size can be calculated as under:

$$*NO\ GO\ size = G \pm H/2 = 25.162 \pm 0.002\ mm$$

$$*GO\ size\ new = (K + z) \pm H/2 = (25.110 + 0.009) \pm 0.002 = 25.119 \pm 0.002\ mm$$

$$*GO\ size\ wear\ limit = K - y = 25.110 - 0 = 25.110\ mm$$

Required Gauge Size for Snap Gauge 270 + 0
- 0.05

The component tolerance will be:

$$G = 270.000\ mm$$

$$K = 270 - 0.05 = 269.950\ mm$$

Snap gauge size can be calculated as under:

$$\dagger GO\ size\ wear\ limit = G + y_1 - \alpha_1 = 270.000 + 0.007 - 0.0004 = 270.003\ mm$$

$$\dagger GO\ size\ new = (G - z_1) \pm H_z = (270.000 - 0.008) \pm 0.006 = 269.992 \pm 0.006\ mm$$

$$\dagger NO\ GO\ size = (K + \alpha_1) \pm H_z = (269.950 + 0.004) \pm 0.006 = 269.954 \pm 0.006\ mm$$

*For actual sizes of plug gauges for standard fits for 1 to 500 mm nominal sizes, refer IS: 7859-1975 'Gauge allowances and manufacturing tolerance for plain gauges for inside measurements for ISO fit sizes (nominal size up to 500 mm)'.

†For actual sizes of snap gauges and ring gauges for standard fits from 1 to 500 mm nominal sizes, refer IS: 7876-1975 'Gauge allowances and manufacturing tolerance for plain gauges for outside measurements for ISO fit sizes (nominal size up to 500 mm)'.

12. General Requirements

12.1 No recommendations are given in this standard for details of the design of gauges. The technical supply conditions shall conform to IS : 7018-1973 ' Technical supply conditions for gauges .

The marking and designation of the gauges shall also conform

to the above Indian Standard.

TABLE 1 MANUFACTURING TOLERANCES FOR GAUGES

Tolerance Grade for Workpiece	IT4		IT5		IT6		IT7		IT8 to IT10		IT11 to IT12		IT13 to IT16	
	Size (IT)	Form (IT)	Size (IT)	Form (IT)	Size (IT)	Form (IT)	Size (IT)	Form (IT)	Size (IT)	Form (IT)	Size (IT)	Form (IT)	Size (IT)	Form (IT)
Tolerance Grade for Cylindrical Plug Gauges	0*	0*	1*	1*	2	1	3	2	3	2	5	4	7	5
Tolerance Grade for Cylindrical Bar Gauges	—	—	—	—	2	1	3	2	3	2	5	4	7	5
Tolerance Grade for Spherical Plug or Disk Gauges	—	—	—	—	2	1	2	1	2	1	4	3	6	5
Tolerance Grade for Spherically Ended Rod Gauges	—	—	—	—	2	1	2	1	2	1	4	3	6	5
Tolerance Grade for Cylindrical Ring Gauges	—	—	—	—	3	2	3	2	4	3	5	4	7	5
Tolerance Grade for Gap Gauges	—	—	—	—	3	2	3	2	4	3	5	4	7	5
Tolerance Grade for Reference Disks for Gap Gauges	—	—	—	—	1	1	1	1	2	1	2	1	3	2
Tolerance Grade for Reference Cylindrical Setting Plug Gauges	—	—	—	—	1	1	1	1	2	1	2	1	3	2
Tolerance Grade for Reference Cylindrical Setting Ring Gauges	—	—	—	—	1	1	1	1	2	1	2	1	3	2

*Up to 6 mm diameter only.

TABLE 2 GAUGE TOLERANCES AND THEIR LOCATION FOR GAUGES FOR INSIDE MEASUREMENTS (HOLES)

(Clause 10.2.2)

All values are in micrometer (μm)

Nominal Sizes m m		Symbols	Work Tolerance Grades as per ISO										
Over	Up to & Incl.		6	7	8	9	10	11	12	13	14	15	16
-	3	T	6	10	14	25	40	60	100	140	250	400	600
		H/2	0.6	1		1		2		5		5	
		Y	1	1.5	3	0		0		0		0	
		Z	1	1.5	2	5		10		20		40	
3	6	T	8	12	18	30	48	75	120	180	300	480	750
		H/2	0.75	1.25		1.25		2.5		6		6	
		Y	1	1.5	3	0		0		0		0	
		Z	1.5	2	3	6		12		24		48	
6	10	T	9	15	22	36	58	90	150	220	360	580	900
		H/2	0.75	1.25		1.25		3		7.5		7.5	
		H _s /2	0.75	0.75		0.75		2		4.5		4.5	
		Y	1	1.5	3	0		0		0		0	
10	18	T	11	18	27	43	70	110	180	270	430	700	1100
		H/2	1	1.5		1.5		4		9		9	
		H _s /2	1	1		1		2.5		5.5		5.5	
		Y	1.5	2	4	0		0		0		0	
18	30	T	13	21	33	52	84	130	210	330	520	840	1300
		H/2	1.25	2		2		4.5		10.5		10.5	
		H _s /2	1.25	1.25		1.25		3		6.5		6.5	
		Y	1.5	3	4	0		0		0		0	
30	50	T	16	25	39	62	100	160	250	390	620	1000	1600
		H/2	1.25	2		2		5.5		12.5		12.5	
		H _s /2	1.25	1.25		1.25		3.5		8		8	
		Y	2	3	5	0		0		0		0	
50	80	T	19	30	46	74	120	190	300	460	740	1200	1900
		H/2	1.5	2.5		2.5		6.5		15		15	
		H _s /2	1.5	1.5		1.5		4		9.5		9.5	
		Y	2	3	5	0		0		0		0	
50	80	Z	2.5	4	7	13		25		48		90	

(Continued)

**TABLE 2 GAUGE TOLERANCES AND THEIR LOCATION FOR GAUGES
FOR INSIDE MEASUREMENTS (HOLES) — Contd**

All values are in micrometer (μm)

Nominal Sizes m m		Symbols	Work Tolerance Grades as per ISO										
Over	Up to & Incl.		6	7	8	9	10	11	12	13	14	15	16
80	120	T	22	35	54	87	140	220	350	540	870	1400	2200
		H/2	2	3		3		7.5		17.5		17.5	
		H _s /2	2	2		2		5		11		11	
		Y	3	4	6	0		0		0		0	
		Z	3	5	8	15		28		54		100	
120	180	T	25	40	63	100	160	250	400	630	1000	1600	2500
		H/2	2.5	4		4		9		20		20	
		H _s /2	2.5	2.5		2.5		6		12.5		12.5	
		Y	3	4	6	0		0		0		0	
		Z	4	6	9	18		32		60		110	
180	250	T	29	46	72	115	185	290	460	720	1150	1850	2900
		H/2	3.5	5		5		10		23		23	
		H _s /2	3.5	3.5		3.5		7		14.5		14.5	
		Y	4	6	7	0		0		0		0	
		Z	5	7	12	21	24	40	45	80	100	170	210
		α	2	3	4	4	7	10	15	25	45	70	110
250	315	T	32	52	81	130	210	320	520	810	1300	2100	3200
		H/2	4	6		6		11.5		26		26	
		H _s /2	4	4		4		8		16		16	
		Y	5	7	9	0		0		0		0	
		Z	6	8	14	24	27	45	50	90	110	190	240
		α	3	4	6	6	9	15	20	35	55	90	140
315	400	T	36	57	89	140	230	360	570	890	1400	2300	3600
		H/2	4.5	6.5		6.5		12.5		28.5		28.5	
		H _s /2	4.5	4.5		4.5		9		18		18	
		Y	6	8	9	0		0		0		0	
		Z	7	10	16	28	32	50	65	100	125	210	280
		α	4	6	7	7	11	15	30	45	70	110	180
400	500	T	40	63	97	155	250	400	630	970	1550	2500	4000
		H/2	5	7.5		7.5		13.5		31.5		31.5	
		H _s /2	5	5		5		10		20		20	
		Y	7	9	11	0		0		0		0	
		Z	8	11	18	32	37	55	70	110	145	240	320
		α	5	7	9	9	14	20	35	55	90	140	220

**TABLE 3 GAUGE TOLERANCES AND THEIR LOCATIONS FOR GAUGES FOR
OUTSIDE MEASUREMENTS (SHAFTS)**

(Clause 10.3.2)

All values are in micrometer (μm)

Nominal Sizes mm		Symbols	Work Tolerance Grades as per ISO											
Over	Up to & incl.		5	6	7	8	9	10	11	12	13	14	15	16
—	3	T	4	6	10	14	25	40	60	100	140	250	400	600
		H _i /2	0.6	1	1.5	1.5	2	5	5					
		H _p /2	0.4	0.4	0.6	0.6	0.6	1	1					
		Y ₁	1	1.5	3	0	0	0	0					
		Z ₁	1	1.5	2	5	10	20	40					
3	6	T	5	8	12	18	30	48	75	120	180	300	480	750
		H _i /2	0.75	1.25	2	2	2.5	6	6					
		H _p /2	0.5	0.5	0.75	0.75	0.75	1.25	1.25					
		Y ₁	1	1.5	3	0	0	0	0					
		Z ₁	1	2	3	6	12	24	48					
6	10	T	6	9	15	22	36	58	90	150	220	360	580	900
		H _i /2	0.75	1.25	2	2	3	7.5	7.5					
		H _p /2	0.5	0.5	0.75	0.75	0.75	1.25	1.25					
		Y ₁	1	1.5	3	0	0	0	0					
		Z ₁	1	2	3	7	14	28	56					
10	18	T	8	11	18	27	43	70	110	180	270	430	700	1100
		H _i /2	1	1.5	2.5	2.5	4	9	9					
		H _p /2	0.6	0.6	1	1	1	1.5	1.5					
		Y ₁	1.5	2	4	0	0	0	0					
		Z ₁	1.5	2.5	4	8	16	32	64					
18	30	T	9	13	21	33	52	84	130	210	330	520	840	1300
		H _i /2	1.25	2	3	3	4.5	10.5	10.5					
		H _p /2	0.75	0.75	1.25	1.25	1.25	2	2					
		Y ₁	2	3	4	0	0	0	0					
		Z ₁	1.5	3	5	9	19	36	72					
30	50	T	11	16	25	39	62	100	160	250	390	620	1000	1600
		H _i /2	1.25	2	3.5	3.5	5.5	12.5	12.5					
		H _p /2	0.75	0.75	1.25	1.25	1.25	2	2					
		Y ₁	2	3	5	0	0	0	0					
		Z ₁	2	3.5	6	11	22	42	80					
50	80	T	13	19	30	46	74	120	190	300	460	740	1200	1900
		H _i /2	1.5	2.5	4	4	6.5	15	15					
		H _p /2	1	1	1.5	1.5	1.5	2.5	2.5					
		Y ₁	2	3	5	0	0	0	0					
		Z ₁	2	4	7	13	25	48	90					

(Continued)

TABLE 3 GAUGE TOLERANCES AND THEIR LOCATIONS FOR GAUGES FOR OUTSIDE MEASUREMENTS (SHAFTS) — Contd

All values are in micrometer (μm)

Nominal Sizes mm		Symbols	Work Tolerance Grades as per ISO											
Over	Up to & Incl.		5	6	7	8	9	10	11	12	13	14	15	16
80	120	T	15	22	35	54	87	140	220	350	540	870	1400	2200
		H ₁ /2	2	3	5	5	7.5	17.5	17.5					
		H _p /2	1.25	1.25	2	2	2	3	3					
		Y ₁	3	4	6	0	0	0	0					
		Z ₁	2.5	5	8	15	28	54	100					
120	180	T	18	25	40	63	100	160	250	400	630	1000	1600	2500
		H ₁ /2	2.5	4	6	6	9	20	20					
		H _p /2	1.75	1.75	2.5	2.5	2.5	4	4					
		Y ₁	3	4	6	0	0	0	0					
		Z ₁	3	6	9	18	32	60	110					
180	250	T	20	29	46	72	115	185	290	460	720	1150	1850	2900
		H ₁ /2	3.5	5	7	7	10	23	23					
		H _p /2	2.25	2.25	3.5	3.5	3.5	5	5					
		Y ₁	3	5	6	7	0	0	0					
		Z ₁	4	7	12	21	24	40	45	80	100	170	210	
		α_1	1	2	3	4	4	7	10	15	25	45	70	110
250	315	T	23	32	52	81	130	210	320	520	810	1300	2100	3200
		H ₁ /2	4	6	8	8	11.5	26	26					
		H _p /2	3	3	4	4	4	6	6					
		Y ₁	3	6	7	9	0	0	0					
		Z ₁	5	8	14	24	27	45	50	90	110	190	240	
		α_1	1.5	3	4	6	6	9	15	20	35	55	90	140
315	400	T	25	36	57	89	140	230	360	570	890	1400	2300	3600
		H ₁ /2	4.5	6.5	9	9	12.5	28.5	28.5					
		H _p /2	3.5	3.5	4.5	4.5	4.5	6.5	6.5					
		Y ₁	4	6	8	9	0	0	0					
		Z ₁	6	10	16	28	32	50	65	100	125	210	280	
		α_1	2.5	4	6	7	7	11	15	30	45	70	110	180
400	500	T	27	40	63	97	155	250	400	630	970	1550	2500	4000
		H ₁ /2	5	7.5	10	10	13.5	31.5	31.5					
		H _p /2	4	4	5	5	5	7.5	7.5					
		Y ₁	4	7	9	11	0	0	0					
		Z ₁	7	11	18	32	37	55	70	110	145	240	320	
		α_1	3	5	7	9	9	14	20	35	55	90	140	220

EXPLANATORY NOTE

This standard was originally issued in 1966 with a view to introducing a uniform gauging practice in the country. The method of specifying the tolerance for gauges and also the calculation of gauge limits was based on the proposals then under consideration at the level of Technical Committee ISO/TC 3 Limits and Fits.

In this revision, the gauging practice for inspection of plain workpieces has been elaborated in detail and it is based on Draft ISO Recommendation No: 1938 ISO system of limits and fits: Part II Inspection of plain workpieces. In the present version, not only have the tolerances for the gauges been indicated but also the gauging principles have been enumerated and recommendations on the use of gauges for various size ranges have been elaborated. The numerical values given in this standard are expressed in terms of the various grades of tolerances provided for in IS : 919-1963. These are, therefore, valid for the ISI system of tolerances only. However, all other requirements of a more general nature given in this standard may still be applied as a rule to any system of limits for plain workpieces.

In the earlier version, not only the tolerances for the limit gauges were covered but also certain requirements on the surface finish hardness, etc, of the gauges were incorporated. Since these requirements are now being covered separately in Indian Standard Technical supply conditions for gauges and measuring devices (*under preparation*), these have been deleted in the present revision.