

Errata for 2009 Uniform Plumbing Code – 2nd Printing

The following is a list of changes that we found after the second printing of the 2009 Uniform Plumbing Code. These changes may or may not apply to your code book. However, we do encourage you to check your code book with this list to ensure that all the changes are updated. Thank you.

Chapter 8

Section 804.1:

The third sentence contains an editorial error. Correct sentence to read as follows: No trap for any clothes washer standpipe receptor shall be installed below the floor, but shall be roughed in not less than six (6) inches (152 mm) and not more than eighteen (18) inches (457 mm) above the floor.

Chapter 13

Section 1316.2 – 1316.6:

Section numbers 1316.2 through 1316.6 were numbered incorrectly. Correct section numbers to read 1316.4 through 1316.8.