

X

इंटरनेट

Disclosure to Promote the Right To Information

Whereas the Parliament of India has set out to provide a practical regime of right to information for citizens to secure access to information under the control of public authorities, in order to promote transparency and accountability in the working of every public authority, and whereas the attached publication of the Bureau of Indian Standards is of particular interest to the public, particularly disadvantaged communities and those engaged in the pursuit of education and knowledge, the attached public safety standard is made available to promote the timely dissemination of this information in an accurate manner to the public.

"जानने का अधिकार, जीने का अधिकार" Mazdoor Kisan Shakti Sangathan "The Right to Information, The Right to Live"

"पुराने को छोड नये के तरफ" Jawaharlal Nehru "Step Out From the Old to the New"

मानक

IS 1367-19 (1997): Industrial fasteners - Threaded steel fasteners - Technical supply conditions, Part 19: Axial load fatigue testing of bolts, screws and studs [PGD 31: Bolts, Nuts and Fasteners Accessories]

> "ज्ञान से एक नये भारत का निर्माण″ Satyanarayan Gangaram Pitroda "Invent a New India Using Knowledge"

RIGHT TO INFORMATION "ज्ञान एक ऐसा खजाना है जो कभी चुराया नहीं जा सकता Bhartrhari-Nītiśatakam "Knowledge is such a treasure which cannot be stolen"





611111111

Made Available By Public. Resource. Org







BLANK PAGE



PROTECTED BY COPYRIGHT

IS 1367 (Part 19): 1997 ISO 3800: 1993

भारतीय मानक

औद्योगिक बन्धक – इस्पात के चूड़ीदार बन्धक – तकनीकी पूर्ति शर्तें

भाग 19 काबले, पेंच एवं स्टड्स का अक्षीय भार श्रान्ति परीक्षण

Indian Standard

INDUSTRIAL FASTENERS — THREADED STEEL FASTENERS — TECHNICAL SUPPLY CONDITIONS PART 19 AXIAL LOAD FATIGUE TESTING OF BOLTS, SCREWS AND STUDS

ICS 21.060.10; 19.060

© BIS 1997

BUREAU OF INDIAN STANDARDS MANAK BHAVAN, 9 BAHADUR SHAH ZAFAR MARG NEW DELHI 110002

May 1997

Price Group 9

IS 1367 (Part 19) : 1997 ISO 3800 : 1993

Indian Standard INDUSTRIAL FASTENERS — THREADED STEEL FASTENERS — TECHNICAL SUPPLY CONDITIONS

PART 19 AXIAL LOAD FATIGUE TESTING OF BOLTS, SCREWS AND STUDS

NATIONAL FOREWORD

This Indian Standard (Part 19) which is identical with ISO 3800 : 1993 'Threaded fasteners — Axial load fatigue testing — Test methods and evaluation of results', issued by the International Organization for Standardization (ISO), was adopted by the Bureau of Indian Standards on the recommendation of Bolts, Nuts and Fasteners Accessories Sectional Committee and approval of the Light Mechanical Engineering Division Council.

The text of the International Standard has been approved as suitable for publication as an Indian Standard without deviation. Certain terminology and conventions are not identical with those used in Indian Standards. Attention is drawn to the following:

- a) Wherever the words 'International Standard' appear, referring to this standard, they should be read as 'Indian Standard'.
- b) Comma (,) has been used as a decimal marker while in Indian Standards the current practice is to use a point (.) as the decimal marker.

In this adopted standard, reference appears to certain International Standards for which Indian Standards ards also exist. The corresponding Indian Standards which are to be substituted in their place are listed below along with their degree of equivalence for the editions indicated:

International Standard	Corresponding Indian Standard	Degree of Equivalence
ISO 273 : 1979	IS 1821 : 1987 Dimensions for clearance holes for bolts and screws (<i>third revision</i>)	Identical
ISO 554 : 1976	IS 196 : 1966 Atmospheric conditions for testing (<i>revised</i>)	Technically equivalent
ISO 885 : 1976	IS 4172 : 1987 Dimensions for radii under the head of bolts and screws (<i>first revision</i>)	Identical
ISO 4032 : 1986	IS 1364 (Part 3): 1992 Hexagon head bolts, screws and nuts of product grades A and B : Part 3 Hexagon nuts (size range M1.6 to M64) (<i>third revision</i>)	Identical
ISO 4033 : 1979	IS/ISO 4033 : 1979 Hexagon nuts, Style 2, Product grades A and B	Identical
ISO 8673 : 1988	IS 13722 : 1993 Hexagon nuts, Style 1, with metric fine pitch threads — Product grades A and B	Identical
ISO 8674 : 1988	IS 13723 : 1994 Hexagon nuts Style 1, with metric fine pitch threads — Product grades A and B 1	Identical

IS 1367 (Part 19) : 1997 ISO 3800 : 1993

This standard (Part 19) covers Technical supply conditions in respect of Axial Load Fatigue Testing of Bolts, Screws and Studs. Other parts covering various aspects of the threaded steel fasteners and their respective degree of equivalence with International Standards are as under:

IS No.	Title	Corresponding ISO Standard and Degree of Equivalence
IS 1367	Technical supply conditions for threaded steel fasteners:	_
(Part 1): 1980	Introduction and general information (<i>second revision</i>)	ISO 8992:1986 Not technically equivalent
(Part 2):1979	Product grades and tolerances (<i>second revision</i>)	Technically equivalent to ISO 4759-1 : 1978
(Part 3): 1991	Mechanical properties and test methods for bolts, screws and studs with full loadability (<i>third revision</i>)	Identical to ISO 898–1 : 1988
(Part 5): 1980	Mechanical properties and test methods for set screws and similar threaded fasteners not under tensile stresses (<i>second revision</i>)	Technically equivalent to ISO 898-5 : 1980
(Part 6): 1994	Mechanical properties and test methods for nuts with specified proof loads (<i>third revision</i>)	Identical to ISO 898-2 : 1992
(Part 7): 1980	Mechanical properties and test methods for nuts without specified proof loads (<i>second revision</i>)	Does not exist
(Part 8):1980	Mechanical and performance properties for prevailing torque type steel hexagon nuts (<i>second revision</i>)	Technically equivalent to ISO 2320 : 1983
(Part 9/Sec 1):1993	Surface discontinuities, Section 1 Bolts, screws and studs for general applications (<i>third revision</i>)	Identical to ISO 6157-1 : 1988
(Part 9/Sec 2):1993	Surface discontinuities, Section 2 Bolts, screws and studs for special applications (third revision)	Identical to ISO 6175-3 : 1988
(Part 10) : 1979	Surface discontinuities on nuts (<i>second</i> revision)	Technically equivalent to ISO 6175-2 : 1995
(Part 11): 1996	Electroplated coatings (third revision)	Identical to ISO 4042 : 1989

IS 1367 (Part 19): 1997 ISO 3800: 1993

IS No.	Title	Corresponding ISO Standard and Degree of Equivalence
(Part 12) : 1981	Phosphate coatings on threaded fasteners (<i>second revision</i>)	Does not exist
(Part 13) : 1983	Hot-dip galvanized coatings on threaded fasteners(second revision)	Does not exist
(Part 14) : 1984	Stainless steel threaded fasteners (<i>second revision</i>)	Technically equivalent to ISO 3506 : 1979
(Part 16) : 1979	Designation system and symbols (<i>second revision</i>)	Does not exist
(Part 17) : 1996	Inspection, sampling and acceptance procedure (<i>third revision</i>)	Identical to ISO 3269 : 1988
(Part 18) : 1996	Packaging (second revision)	Does not exist
(Part 20): 1996	Torsional test and minimum torques for bolts and screws with nominal diameter 1 mm to 10 mm	Identical to ISO 898-7 : 1992

NOTE — Formulation of Part 4 and Part 15 of this standard purported to cover 'Mechanical properties and test methods for bolts, screws and studs with reduced loadability' and 'Requirements at subzero and elevated temperatures' respectively, will await corresponding International agreement.

For the purpose of deciding whether a particular requirement of this standard is complied with, the final value, observed or calculated, expressing the result of a test or analysis, shall be rounded off in accordance with IS 2 : 1960 'Rules for rounding off numerical values (*revised*)'. The number of significant places retained in the rounded off value should be the same as that of the specified value in this standard.

As in the Original Standard, this Page is Intentionally Left Blank

Indian Standard INDUSTRIAL FASTENERS — THREADED STEEL FASTENERS — TECHNICAL SUPPLY CONDITIONS

PART 19 AXIAL LOAD FATIGUE TESTING OF BOLTS, SCREWS AND STUDS

1 Scope

This International Standard specifies the conditions for carrying out axial load fatigue tests on threaded fasteners, as well as recommendations for the evaluation of the results.

Unless otherwise agreed, the tests are of the fluctuating tension type and are carried out at room temperature, the loading applied being centric along the longitudinal axis of the fastener. The influence of the compliance of clamped parts on the strain of the fastener is not taken into account.

This method allows determination of the fatigue strength of threaded fasteners.

The test results can be influenced by the test conditions. For this reason, minimum requirements are specified to reduce this effect. In addition, calibration and centring control methods for the testing apparatus are included.

2 Normative references

The following standards contain provisions which, through reference in this text, constitute provisions of this International Standard. At the time of publication, the editions indicated were valid. All standards are subject to revision, and parties to agreements based on this International Standard are encouraged to investigate the possibility of applying the most recent reditions of the standards indicated below. Members of IEC and ISO maintain registers of currently valid International Standards.

ISO 273:1979, Fasteners — Clearance holes for bolts and screws.

ISO 554:1976, Standard atmospheres for conditioning and/or testing — Specifications.

ISO 885:1976, General purpose bolts and screws — Metric series — Radii under the head.

ISO 4032:1986, Hexagon nuts, style 1 — Product grades A and B.

ISO 4033:1979, Hexagon nuts, style 2 — Product grades A and B.

ISO 8673:1988, Hexagon nuts, style 1, with metric fine pitch thread — Product grades A and B.

ISO 8674:1988, Hexagon nuts, style 2, with metric fine pitch thread — Product grades A and B.

3 Symbols and their designations

See table 1.

Table 1 — Symbols and their designations

Symbol	Designation						
A _{d3}	Area at nominal minor diameter, $A_{d3} \approx \pi d_3^2/4$						
As	Stress area $A_{\rm s} = \frac{\pi}{4} \left(\frac{d_2 + d_3}{2} \right)^2$						
	Area to be used in calculation's of mean stress and stress amplitude. By agreement between the user and supplier, <i>A</i> _{a3} may be used.						
d	Nominal size of the thread of the load verification stud						
<i>d</i> ₁	Basic minor diameter of the thread						
d ₂	Basic pitch diameter of the thread						
d ₃	Nominal minor diameter of the thread, $d_3 = d_1 - \frac{H}{6}$						
da	Diameter at the point of tangency of the fillet						
$d_{\rm h}$	Clearance hole diameter						
d _s	Shank diameter of the load verification stud						
D	Nominal thread diameter of the threaded test adaptor						
F	Tensile load						
F _{0,2}	Tensile load at proof stress $R_{p0,2}$						
Fa	Load amplitude						
ΔF_{aII}	Difference of load amplitudes in the transition range						
F _A	Load amplitude at endurance fatigue limit						
F _m	Mean load						
H	Height of the fundamental triangle of the thread						
N	Number of stress cycles						
N _G	The number of stress cycles in the case where the test has discontinued without failure						
р	Failure probability						
<i>P</i> f	Failure probability in the finite life range						
p _t	Failure probability in the transition range						
Р	Pitch of the thread						
R _{m,min}	Minimum tensile strength						

4 Principle

Test are made on threaded fasteners to determine fatigue properties such as those shown by the Wöhler curve (S/N curve).

Threaded fasteners to be tested are mounted in an axial load fatigue testing machine and subjected to fluctuating tension type loading.

Symbol	Designation
R _s	Constant stress ratio $\sigma_{\min}/\sigma_{\max}$
S	Width across flats of hexagons
$S(F_A)$	Standard deviation of the fatigue load
$S(\sigma_A)$	Standard deviation of the fatigue strength
$S(\log N)$	Standard deviation of logarithm of the fatigue life
α,β	Coefficients of regression line for the inclined part of <i>S/N</i> curve
σ_{a}	Stress amplitude
σ_{A}	Stress amplitude at endurance fatigue limit
$\sigma_{\sf ax}$	Axial tensile stress
σ_{b}	Bending stress
σ _m	Mean stress
σ_{min}	Minimum stress
$\sigma_{\sf max}$	Maximum stress
σ _{Miń}	Minimum stress at endurance fatigue limit
σ_{Max}	Maximum stress at endurance fatigue limit
σ_{AN}	Fatigue strength at N cycles
σ_{AA}	Estimated value of finite life strength at $N = 5 \times 10^4$
σ_{AB}	Estimated value of finite life strength at $N = 1 \times 10^6$
$\sigma_{a,i}$	Stress amplitude of the <i>i</i> th test in the finite life range
σ _{a,j}	Stress amplitude of the j^{th} test by staircase method
$\Delta\sigma_{ m aI}$	Interval of stress amplitude of the test at the finite life range (inclined part of S/N curve)
$\Delta\sigma_{ m aII}$	Difference in levels of stress amplitude in the tran- sition range
NOTES	

1 The symbol \wedge is used in the case of estimated values. For example, the estimated value $\hat{\sigma}_{AN}$ of the fatigue strength at the number of cycles *N*.

2 The symbol – is used in the case of σ_a or log N values which are derived from the regression line; e.g. $\overline{\sigma_a}$ or $\overline{\log N}$.

Tests with constant mean stress σ_m or constant stress ratio $R_s = \sigma_{min}/\sigma_{max}$ may be used. Constant mean stress is used generally to determine infinite life [see case (c) in figure 10].

Constant stress ratio is generally for quality acceptance testing [see case (a) in figure 10]. The test is continued until the test piece fails, or until a predetermined number of stress cycles has been exceeded. Generally the number of test cycles is determined by the material or by the endurance fatigue strength of the test specimen. Unless otherwise specified, the definition of failure is complete separation of the fastener into two parts.

5 Apparatus

5.1 Testing machine

The testing machine shall be capable of maintaining automatically the loads to within ± 2 % of the required values throughout the test and shall be equipped with a device for counting and recording the

total number of cycles per test. The testing machine shall be calibrated periodically to ensure this accuracy. The frequency range of testing shall be between 4,2 Hz and 250 Hz. The testing machine shall induce a sinusoidal fluctuation in load in the test piece.

The testing machine shall have a device to prevent its automatic restarting after stopping due to electrical power service interruption.

5.2 Test fixtures

The test fixtures shall be capable of transmitting an axial load to the test piece. Figures 1 and 2 give basic requirements. Self-aligning devices are not recommended, see 5.3.

Perpendicularity and concentricity tolerances in



d_h is in accordance with ISO 273, fine series.
 d_a is in accordance with ISO 885, finished products.

1) Surface may be case-hardened 0,25 mm to 0,5 mm deep: maximum hardness, HRC 60; minimum hardness, 5 points HRC greater than that of the test part.

Figure 1 — Fixture without insert

IS 1367 (Part 19): 1997 ISO 3800: 1993

Perpendicularity and concentricity tolerances in millimetres, surface roughness in micrometres



d_h is in accordance with ISO 273, fine series.
 d_a is in accordance with ISO 885, finished products.

 The use of an insert shall not affect the rigidity of the test fixture.
 Surface may be case-hardned 0.25 mm to 0.5 mm deep: maximum hardness, HRC 60; minimum hardness, 5 points HRC greater than that of the test part.



5.3 Test alignment

Periodically, the alignment of the test set-up shall be verified. This shall be determined by using a load verification stud (see figure 3) with four strain gauges located at 90° on a common centreline around the axis. The length of the parallel part of the load verification stud shall be four times its diameter. When measured at 50 % of the load range used on the machine, the difference between the maximum stress $\sigma_{ax} + \sigma_b$ and the nominal tensile stress σ_{ax} shall not exceed 6 % of the nominal tensile stress (see figure 4).

Self-aligning devices are not recommended. If they are used, alignment shall be checked carefully since

any excentric loading may cause fatigue test results to vary widely.

5.4 Internally threaded component

For fatigue testing of standard products, the appropriate size and property class of nut in accordance with ISO 4032, ISO 4033, ISO 8673 or ISO 8674 or a threaded adapter shall be used.

If special bolt-nut combinations are tested, a precise description of the nut shall be given as specified in 8.2.

If threaded adapters according to figure 5 are used, they shall be described in accordance with 8.2.

Cylindricity, perpendicularity and concentricity tolerances in millimetres, surface roughness in micrometres



1) The tolerance class of the screw thread shall be 4h. 2) $d_s = d$





Figure 4 — Stress distribution in the shank of the load verification stud

Flatness, perpendicularity and concentricity tolerances in millimetres



1) Thread tolerance 6H.



5.5 Test washers

A chamfered test washer may be used under the bolt head to provide clearance for the head-to-shank fillet, or the fixtures may be chamfered. The maximum diameter of the 45° included angle chamfer shall be equal to the diameter at the point of tangency of the fillet (d_a) with a + IT12 tolerance (see figure 6). The faces of washers shall be parallel to within 0,01 mm. The hardness of the washer shall be the same as that of the fixture.

Where a test washer is used, it shall be indicated in the test report (see 8.3).

6 Test procedure

The capacity of the testing machine shall be selected so that the maximum load on the test specimen is equal to or greater than 10 % of the maximum scale capacity of the machine in the test configuration selected. The bearing face of the nut or the face of the threaded adapter shall be located at least four pitches from the unthreaded portion of the shank and the nut threads shall be fully engaged; a bolt length of at least 2P shall protrude beyond the test nut (see figure 7). Test nuts shall be used once only.

Threaded test adapters may be used continually as long as they assemble freely on the externally threaded part each time and no damage has been observed.



Figure 6 — Test washer (assembled)



Figure 7 — Location of test nut

The specimen shall be assembled freely in the fixture without binding or forcing. No torsional stress shall be induced in the assembly by torquing the nut; i.e. the load shall be induced in the assembly by the testing machine.

The threaded fastener and test nut shall be thoroughly cleaned and then coated with SAE 20 oil or equivalent prior to testing.

The test frequency shall be selected so that the temperature of the test specimen does not rise more than 50 °C during the test period. The temperature should be measured at the first engaged thread.

At frequent intervals throughout the test period, the load shall be monitored to ascertain that the load conditions have not changed.

Results of fatigue tests are affected by atmospheric conditions. Therefore, if possible, atmospheric conditions, particularly humidity, should be checked in accordance with ISO 554:1976, 2.1.

7 Evaluation of results

A comparative assessment of fatigue strength values is only possible when the tests and the evaluation of results are carried out in a uniform manner.

Fatigue strength values can be determined in the finite life range (failure of all test pieces before a predetermined number of stress cycles is reached) and in the transition range where, up to the predetermined number of stress cycles (in general 5×10^6 to 10^7 stress cycles), failures as well as non-failures will occur (see figure 10). As a function of the test objective, the fatigue tests are carried out and evaluated according to two methods:

- a) a minimum number of stress cycles is reached at a predetermined stress amplitude in the finite life range and transition range, respectively;
- b) the position and size of scatter of the finite life range and transition range, respectively, are determined using statistical evaluation methods.

7.1 Tests in the finite life range

The test in the finite life range is the test for obtaining the finite fatigue life data of threaded fasteners and is generally applied for production control of products, quality assurance at delivery and the like. When the product specification defines the stress and the number of stress cycles and the other conditions are not specified, generally a minimum of six products should be tested. Furthermore, this test shall be made by using either the method to keep the mean stress (σ_m) constant or the method to keep the ratio (R_s) of the maximum stress and the minimum stress constant $(R_s = 1/10 \text{ is generally used})$.

7.1.1 Quality control test

A statistically valid sample shall be taken for test purposes as agreed between the user and supplier. The sample should be increased by at least 10 % to allow for unforeseen testing difficulties.

7.1.2 **Determination of position and slope of the** finite life range (Design test)

The scatter in the number of stress cycles in the finite life range can economically only be approximated using statistical calculation methods.

For assessment of the finite life range, the fatigue tests shall be carried out on at least two stress levels, which should be chosen so that numbers of stress cycles are obtained between 10^4 and 5×10^5 .

The number of tests (sampling size) per stress level depends on the selected statistical evaluation method and the required prediction reliability for the probabilities of failure p_t ; e.g. $p_t = 10$ %, 50 % or 90 %.

The minimum number of test pieces should not be less than six.

The scatter in the finite life range on one stress level can then be determined by taking as a basis, for example, the normal Gaussian distribution in the Gaussian probability net and by using the estimator

$$p_{t} = \frac{3i-1}{3n+1}$$

where

- *p*_f is the assessed value for the probability of failure in the finite life range;
- *i* is the ordinal number of a test piece;
- *n* is the number of test pieces tested.

The following example explains the procedure:

n = 8 bolts are tested with the constant stress amplitude $\sigma_a = 150 \text{ N/mm}^2$. The stress cycles reached until failure are, in chronological order:

 $N = (169, 178, 271, 129, 405, 115, 280, 305) \times 10^3$.

At first the numbers of stress cycles are arranged according to size, and ordinals *i* are assigned to them.

The first test piece with the lowest number of stress cycles receives the ordinal i = 1, the n^{th} test piece (with the highest number of stress cycles) the ordinal i = n = 8.

This results in the order or evaluation system given in table 2.

Now the numbers of stress cycles belonging to the respective probabilities of failure $p_{\rm f}$ are plotted in a Gaussian probability net (figure 8) and the individual results are replaced by a compensation line (regression line). The limits N_{10} , N_{50} and N_{90} can be read using this compensation line.

EXAMPLE

 $N_{10} = 110 \times 10^3$, $N_{50} = 213 \times 10^3$ and $N_{90} = 415 \times 10^3$ (i.e. 10 % of all test pieces are expected to fail within 110×10^3 stress cycles, 50 % within 213×10^3 stress cycles and 90 % within 415×10^3 stress cycles).

7.2 Tests in the transition range (infinite life range)

7.2.1 Achieving a given number of stress cycles without failure

For checking whether the requirement for a minimum number of stress cycles is satisfied, a minimum of six test pieces shall be tested at the predetermined stress amplitude, unless otherwise agreed between the user and supplier. The sample should be increased by at least 10 % to allow for unforeseen difficulties.

7.2.2 Determination of position and size of the transition range

By analogy with the finite life range, the scatter in the transition range can economically only be approximated using statistical calculation methods.

In practice, two statistical evaluation methods are basically preferred:

- a) stepwise changing of the stress amplitude after each individual test (staircase method);
- b) changing of the stress amplitude after having tested several bolts at a constant stress level (e.g. boundary method, arc sine method).

These evaluation methods are based on model functions which approximately represent the distribution of the population of the test lot.

Therefore the median σ_{A50} (fatigue strength with 50 % probability of failure) and the limits of the transition range (e.g. σ_{A10} , σ_{A90}) are to be determined.

Experience has shown that about 15 to 20 test pieces are necessary in order to be able to determine the fatigue strength σ_{A50} within a tolerance of \pm 5 %.

For the determination of the limits of the transition range, the number of test pieces is clearly higher (e.g. about 20 to 30 test pieces for σ_{A10}).

As to the reliability and accuracy of the values to be obtained, the arc sine, the staircase and boundary methods, which in general are based on the normal Gaussian distribution, are approximately equally good under the same test conditions.

of $\sigma = 150 \text{ N/mm}^2$ in the finite life range	e 2 — Order system foi	tem for the statistical evaluat	ion of 8 fatigue tests	with a stress ampli
		of $\sigma_{\rm a} = 150 \text{ N/mm}^2$ in t	he finite life range	

Ordinal i	1	2	3	4	5	6	7	8
Number of stress cycles $N \times 10^3$ (in ascending order)	115	129	169	178	271	280	305	405
Probability of failure , p_i , % $p_i = \frac{3i - 1}{3n + 1} \times 100$	8	20	32	44	56	68	80	92



 $(N_{10}, N_{50}, N_{90} =$ number of stress cycles with 10 %, 50 % or 90 % probability of failure respectively)

Figure 8 — Probability of failure $p_{\rm f}$ and number of stress cycles in the finite life range, determined on the basis of 8 fatigue tests with $\sigma_{\rm a} = 150 \text{ N/mm}^2$

7.2.3 Procedures of staircase, boundary and arc sine methods

7.2.3.1 Staircase method

Test the first test piece at a stress level which shall be as close as possible to the expected median of the transition range. If failure occurs, decrease stepwise the load for the next test pieces (the same step size) until there is non-failure. After a non-failure, increase the load stepwise until failure occurs. If non-failure is recorded for the first test piece, the procedure is reversed. In practice, the procedure very quickly centres on the median and, in the case of a large number of test pieces and a favourable position of the starting stress level, the frequencies of failure and non-failure are the same or nearly the same. The event occurring less frequently as a whole is used for the calculation.

The evaluation comprises the following steps:

a) expected median

$$F_{A50} = F_{ao} + \Delta F_{aII} \left(\frac{A}{C} \pm x \right)$$

(See explanations of symbols in table 3.)

b) expected standard deviation

$$S(F_{A}) = 1.62\Delta F_{aII} \left(\frac{CE - A^{2}}{C^{2}} + 0.029 \right)$$

where $\frac{CE - A^{2}}{C^{2}}$ shall be > 0.3

(See explanations of symbols in table 3.)

Table 3 shows an example of the evaluation of fatigue tests by the staircase method.

7.2.3.2 Boundary method

The procedure for the boundary method is explained on the basis of figure 9. As the position of the transition range is not known prior to the test and can in general only be approximated, first test a test piece on a first load amplitude. In this case, this load amplitude $F_a = 2500$ N. If this first test piece shows no failure up to the predetermined number of stress cycles $N_{\rm G}$, the load amplitude is subsequently increased until the first test piece fails. In the example, this is the load amplitude $F_{\rm a1} = 4\,000$ N. Carry out several tests on the level on which there is now for the first time an event (failure or non-failure) deviating from the previous tests. Thereby the number of test pieces depends on the required accuracy of the result. In this example, the number of test pieces is eight. For the selection of the second load amplitude, it is advantageous to know the width of the transition range; this allows the second level to be chosen, in a mathematically useful way, at its limit where the expected result becomes more exact.

The following applies to the determination of the second level:

$$F_{a2} = F_{a1} + \Delta F_{aII}$$

with

$$\Delta F_{\text{all}} = \left(1 - \frac{r}{n}\right) BF_{\text{al}} \text{ for } r \leqslant 0,5n$$

or

$$\Delta F_{aII} = -\frac{r}{n} BF_{a1}$$
 for $r \ge 0.5n$

Quantity B takes account of the width of the transition range. For B, a value between 0,15 and 0,2 is recommended.

On the second load amplitude, found in the example in figure 9, again eight test pieces are tested and the probabilities of failure, p_t , are plotted in the Gaussian probability net according to the estimator:

$$p_{\rm t} = \frac{3r-1}{3n+1}$$

[figure 9, b)]

where

- r is the number of failures;
- *n* is the number of test pieces tested.

Using the normal Gaussian distribution, the two points determined can be connected to form a straight line which then allows determination of the median F_{A5C} and of the limiting values, such as F_{A10} and F_{A90} , etc.

Test piece :Hexagon head bolt ISO 4014 - M10 \times 80 - 8.8Mean load F_m : $0,6F_{0,2}$ (N)																					
1								2								3	4	5	6	7	8
<i>F</i> _A (N)			х	Fai	lure						0 1	Non-fa	ailure			×	0	z	f	zf	$z^2 f$
4 700													x			1	0	3	0	0	0
4 300						x		×				0		×		3	1	2	1	2	4
3 900	x		x		0		0		x		0				×	4	3	1	3	3	3
3 500		0		0						0						0	3	0	3	0	0
Test piece No.	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15						
										Sun	n of c	olum	ns 3,	4, 6,	7, 8	8	7		7	5	7
_																			С	Α	Е
$F_{A50} = F_{a0} + \Delta F_{aII} \left(\frac{A}{C} \pm x \right) = 3 \ 929 \ N$ $S(F_A) = 1.62 \Delta F_{aII} \left(\frac{CE - A^2}{C^2} + 0.029 \right) = 177 \ N$																					
Column 1: load amplitude Column 2: indication of event (failure x, non-failure o) Column 3: number of failures per load amplitude Column 4: number of non-failures per load amplitude Column 5: ordinal z, starting with 0 at the lowest load amplitude																					
Column 3.Ordina 2, starting with 0 at the lowest load ampitudeIt is assigned to the event with the lower frequency in columns 3 and 4 respectively. In the example in table 3, it is column 4 with only 7 non-failures as compared to column 3 with 9 failures.Column 6:frequency, repetition of values from column 3 or 4 with the lower sum (here column 4).Column 7:product of columns 5 and 6 (zf)Column 8:product of columns 5 and 7 (z^2f)C, A, E:sum of columns 6, 7 and 8 F_{ao} :lowest load amplitude in columns 3 or 4 with the lower number of events (here column 4, $F_{ao} = 3500$ N) F_{A50} :median, load amplitude with 50 % probability of survival x : $\begin{cases} + 0.5$ when column 6 = column 4 $- 0.5$ when column 6 = column 3 ΔF_{ail} :step (here $\Delta F_{ail} = 400$ N) S standard deviation										nple											

Table 3 — Example of the evaluation of fatigue tests by the staircase method





7.2.3.3 Arc sine method

The procedure for the arc sine method is similar to that for the boundary method. Carry out fatigue tests on several equidistant alternating load levels with the same number of test pieces per level. For each of these levels, calculate the corresponding probabilities of survival using the $\arcsin\sqrt{p}$ transformation, for example,

$$\tau = \arcsin\sqrt{(r+1)/(n+1)} + \arcsin\sqrt{r/(n+1)}$$

Determine the transition range either graphically in a corresponding probability net or mathematically by determining a regression line after the corresponding transformation of the calculated values

7.3 Development of complete Wöhler curve (*S*/*N* curve)

For the development of a complete Wöhler curve, the results of the test according to 7.1.2 and 7.2.2 are represented graphically in figure 10.

7.4 Combined test method

7.4.1 Number of test specimens

At least 14 specimens are required for the test, that is 2 specimens for each of four stress amplitude levels (8 pieces in total) in order to determine the inclined part of the S/N curve, and 6 specimens in order to determine the horizontal part because the staircase method requires a small number of specimens. Since the test does not always proceed, in practice, as shown in figure 11 and there are some cases where more than 14 specimens are required, reserve some extra specimens.



Figure 10 — Wöhler curve (S/N curve) $\sigma_a = f(N)$

م د. ز



NOTE - The numbers in the figure show the order of test.



7.4.2 Test in the finite life range

The test method for the finite life range (inclined part of the S/N curve) is as follows.

Predict the finite life strength σ_{AA} and σ_{AB} of the specimen at $N = 5 \times 10^4$ and $N = 1 \times 10^6$ by referring to existing data on materials of the same class, specimens of the same shape and stress cycles of the same type.

Obtain $\Delta \sigma_{aI} = (\sigma_{AA} - \sigma_{AB})/3$. (Round off the numerical values.) Take this value of $\Delta \sigma_{aI}$ as the initial set value for intervals of the test stress amplitude in the inclined part, and take $\sigma_{AA} + k\Delta \sigma_{aI}$ ($k = \pm 1, \pm 2, ...$) as the initial set value for the test stress amplitude level.

Test the first specimen at the stress amplitude level $\sigma_{a}(1) = \sigma_{AA} - \Delta \sigma_{aI}$.

Test one specimen at a time in the order

$$\sigma_{a}(2) = \sigma_{a}(1) - \Delta \sigma_{aI}, \ \sigma_{a}(3) = \sigma_{a}(2) - \Delta \sigma_{aI}, \ \dots,$$

by lowering the stress amplitude levels by $\Delta \sigma_{aI}$ each time until the first unbroken specimen is obtained¹). In this case, check the value of $\Delta \sigma_{aI}$ as the test progresses, correct it and reset $\Delta \sigma_{aI}$ for subsequent levels, if necessary.¹

Test one specimen at each of the stress amplitude levels at which no specimen has been broken, among the four higher levels adjacent to the level²¹ at which the unbroken specimen has been obtained, so that one broken specimen is obtained at each of those four stress amplitude levels.

$$\sigma_{\mathbf{a}}(2) = \sigma_{\mathbf{a}}(1) + 2\Delta\sigma_{\mathbf{a}\mathbf{i}}, \ \sigma_{\mathbf{a}}(3) = \sigma_{\mathbf{a}}(2) + 2\Delta\sigma_{\mathbf{a}\mathbf{i}}, \dots,$$

2) When there are two or more stress amplitude levels at which no specimen has been broken (this is possible in the case corresponding to footnote ¹), the highest stress amplitude level among them shall be taken.

¹⁾ If the predictions for σ_{AA} and σ_{AB} are notably inadequate, some specimens will not be broken at $\sigma_{a}(1)$. In that case, test one specimen at a time in the order

until the first broken specimen is obtained, by raising the stress amplitude level by $2\Delta\sigma_{aI}$ each time instead of lowering it by $\Delta\sigma_{aI}$.

Carry out the test on the second specimen³¹ at the higher levels of stress amplitude adjacent to the stress amplitude level²¹ at which no specimen has been broken, in ascending order, starting from the lower of those stress amplitude levels, until eight broken specimens in total have been obtained.

Arrange the obtained data of eight broken specimens in a semi-logarithmic graph (σ_a , log N) and obtain S/N curves.

Determine the inclined part and the standard deviation of the S/N curve for a 50 % failure probability by the following formula.

Regression line for the inclined part of the S/N curve is given by:

 $\log N = \hat{\alpha} + \hat{\beta}\sigma_{a}$

where

$$\hat{\alpha} = \overline{\log N} - \hat{\beta}\overline{\sigma_{a}}$$

$$\hat{\beta} = \frac{\sum_{i=1}^{n} [\sigma_{a}(i) - \overline{\sigma_{a}}] [\log N(i) - \overline{\log N}]}{\sum_{i=1}^{n} [\sigma_{a}(i) - \overline{\sigma_{a}}]^{2}} \quad (\text{see note 1})$$

$$\overline{\log N} = \frac{1}{8} \sum_{i=1}^{n} \log N(i) \text{ (see note 1)}$$

$$\overline{\sigma_{a}} = \frac{1}{8} \sum_{i=1}^{n} \sigma_{a}(i) \text{ (see note 1)}$$

Estimated value of the standard deviation $S(\log N)$ of the logarithm of the fatigue life is given by:

$$\hat{S}(\log N) = \left[\frac{1}{6}\sum_{i=1}^{n} \left(\log N(i) - \left[\hat{\alpha} + \hat{\beta}\sigma_{a}(i)\right]\right)^{2}\right]^{1/2}$$

(see note 1)

Estimated value of the standard deviation $S(\sigma_a)$ of the fatigue strength is given by:

$$\hat{S}(\sigma_{a}) = \frac{1}{|\hat{\beta}|} \hat{S}(\log N)$$

NOTE 3 In the tests carried out on the first to the n^{th} specimen, use the data from eight broken specimens, in the

order from the lowest of the stress amplitude levels at each of which two specimens have been broken at the same stress amplitude.

7.4.3 Method of testing fatigue strength at $N_{\rm G} = 5 \times 10^6$

The method of testing fatigue strength, in which the test is cut off at the number of cycles $(N_{\rm G})$ of 5×10^6 , is as follows.

Use the staircase method with a small number of samples to estimate the fatigue strength at $N_{\rm G} = 5 \times 10^6$.

Take as the test stress amplitude $\sigma_a(1)$ applied to the first specimen by the staircase method, the stress amplitude level at which no specimen was broken (take the highest stress amplitude level when such stress amplitude levels are two or more). However, one unbroken specimen has already been obtained at the level σ_a , this shall be regarded as the test result on the first specimen by the staircase method and the test at σ_a is not carried out again.

The successive difference $\Delta \sigma_{aII}$, in levels of stress amplitude in the staircase method shall be the estimated value $\hat{S}(\sigma_a)$ of the standard deviation of the fatigue strength with time (the numerical value shall be rounded off properly).

$$\Delta \sigma_{a\Pi} = \hat{S}(\sigma_a)$$

Carry out the test on the second specimen at the level

$$\sigma_{\rm a}(2) = \sigma_{\rm a}(1) + \Delta \sigma_{\rm aII}$$

Carry out the test on the third to sixth specimens at the levels

$$\sigma_{a}(j) = \sigma_{a}(j-1) \pm \Delta \sigma_{aII} \ (j=3, 4, 5, 6)$$

where the minus sign shall be taken when the $(j-1)^{th}$ specimen is broken and the plus sign when it is not broken.

Obtain the test stress amplitude applied to the seventh specimen from

$$\sigma_{\rm a}(7) = \sigma_{\rm a}(6) \pm \Delta \sigma_{\rm aff}$$

where the minus sign shall be taken when the specimen is broken at $\sigma_a(6)$ and the plus sign when it is not broken. However, the test on the seventh specimen is not actually carried out.

³⁾ If the second specimen is not broken at a certain stress amplitude level, add one more test at the required stress amplitude level so that two broken specimens can be obtained each of the four higher levels of stress amplitude adjacent to that stress amplitude level.

Estimate the fatigue strength σ_{AN} for the failure probability p = 50 % at $N = 5 \times 10^6$ from the following formula:

$$\hat{\sigma}_{AN} = \frac{1}{6} \sum_{j=2}^{7} \sigma_{a}(j)$$

7.4.4 Determination of Wöhler curve (S/N curve)

The Wöhler curve (S/N curve) (see figure 12) for the failure probability p = 10 % and 90 % can be obtained by the following formula.

Inclined part:

$$\log N = \hat{\alpha} + \hat{\beta}\sigma_{a} \pm 1,28\hat{S}(\log N)$$

Horizontal part:

$$\sigma_{\rm a} = \hat{\sigma}_{\rm AN} \pm \frac{1.28}{\left|\hat{\beta}\right|} \hat{S}(\log N)$$

The double signs of the formulae shall be minus for p = 10 % and plus for p = 90 %.

7.5 Development of a Haigh diagram

To select a fastener correctly, a designer may need additional information concerning the influence of mean stress on the fatigue strength. The Haigh diagram (figure 13) presents the required data in a convienent form and shows the fatigue strength for 10 %, 50 % and 90 % probability of failure. Using statistical methods as defined in 7.2 or 7.4, this chart may be developed using a minimum number of parts, on each of the following mean stress levels:

- a) high constant mean stress $\sigma_m = 0.7R_{m,min}$;
- b) medium constant mean stress $\sigma_m = 0.4R_{m,min}$;
- c) low mean stress $\sigma_{\rm m} = 1,22\sigma_{\rm A}$ (for $R_{\rm s} = 0,1$).

Other mean stresses may be used by agreement between the user and supplier.

8 Test report

In reporting fatigue data, the test conditions shall be clearly defined and the test report shall include details of the following (deviations from this International Standard shall be pointed out clearly).

8.1 Definition of externally threaded fastener:

- a) type and property class designation (if applicable);
- b) thread size, pitch, length of fastener, thread tolerance and profile;
- c) manufacturing method of fastener and thread;
- actual mechanical properties (tensile strength and proof stress);
- e) surface coating and supplementary lubrication;
- f) nut or adapter location (distance from nut or adapter face to thread runout);
- g) raw material.
- 8.2 Definition of internally threaded component:
- a) type and property class of nut or height of threaded test adapter;
- b) actual hardness;
- c) raw material;
- d) surface coating and supplementary lubricant.
- **8.3** Application of test washer.

8.4 Type and frequency of testing machine.

8.5 Stress area used in the calculation $(A_s, A_{d3} \text{ or other})$.

8.6 Type of stress cycle (for example, mean stress and stress amplitude or R_s and either σ_{min} or σ_{max}).

8.7 Location of failure.

8.8 The applied statistical evaluation methods.

8.9 Atmospheric conditions (range of temperature and humidity during test).







Figure 13 — Haigh diagram

Bureau of Indian Standards

BIS is a statutory institution established under the *Bureau of Indian Standards Act*, 1986 to promote harmonious development of the activities of standardization, marking and quality certification of goods and attending to connected matters in the country.

Copyright

BIS has the copyright of all its publications. No part of these publications may be reproduced in any form without the prior permission in writing of BIS. This does not preclude the free use, in the course of implementing the standard, of necessary details, such as symbols and sizes, type or grade designations. Enquiries relating to copyright be addressed to the Director (Publications), BIS.

Review of Indian Standards

Amendments are issued to standards as the need arises on the basis of comments. Standards are also reviewed periodically; a standard along with amendments is reaffirmed when such review indicates that no changes are needed; if the review indicates that changes are needed, it is taken up for revision. Users of Indian Standards should ascertain that they are in possession of the latest amendments or edition by referring to the latest issue of 'BIS Handbook' and 'Standards : Monthly Additions'.

This Indian Standard has been developed from Doc : No. LM 14 (0045).

Amendments Issued Since Publication

Amend No.	Date of Issue	Text Affected
	· · · · · · · · · · · · · · · · · · ·	·
	· · · · · · · · · · · · · · · · · · ·	
	······	
	BUREAU OF INDIAN STANDA	ARDS
Headquarters:		
Manak Bhavan, 9 Bah Telephones : 323 01 3	adur Shah Zafar Marg, New Delhi 110002 1, 323 94 02, 323 33 75	Telegrams: Manaksanstha (Common to all offices)
Regional Offices:		Telephone
Central : Manak Bhav NEW DELH	an, 9 Bahadur Shah Zafar Marg [110002	{ 323 76 17 323 38 41
Eastern : 1/14 C. I. T. CALCUTTA	Scheme VII M, V. I. P. Road, Maniktola 700054	337 84 99, 337 85 61 337 86 26, 337 86 62
Northern : SCO 335-3	36, Sector 34-A, CHANDIGARH 160022	<pre>{ 60 38 43 60 20 25</pre>
Southern : C. I. T. Can	npus, IV Cross Road, CHENNAI 600113	235 02 16, 235 04 42 235 15 19, 235 23 15
Western : Manakalaya MUMBAI 4	, E9 MIDC, Marol, Andheri (East) 00093	<pre>{ 832 92 95, 832 78 58 832 78 91, 832 78 92</pre>
Branches : AHMADA COIMBAT KANPIR	BAD. BANGALORE. BHOPAL. ORE, FARIDABAD. GHAZIABAD. GUWAHATI. LUCKNOW NAGPUR. PATNA. PUNE THU	BHUBANESHWAR. HYDERABAD. JAIPUR. RUVANANTHAPURAM