

Errata for 2009 Uniform Mechanical Code – 2nd Printing (October 2010)

The following is a list of changes that we found after the second printing of the 2009 Uniform Mechanical Code. These changes may or may not apply to your codebook. However, we do encourage you to check your codebook with this list to ensure that all the changes are updated. Thank you.

Chapter 5

Section 517.7.7 Section number reference reads 517.9. Correct to read 513.2.2.1 (2).

Chapter 10

Section 1003.15 Definition for alpha letter O not referenced, renumber remaining alpha letters.

Chapter 13

Section 1309.5.3.4 Abbreviation for standard reads IAS, revise to CSA.
Section 1312.2.1 Section number reference reads 1311.1.4. Correct to read 1312.1.4.
Section 1312.2.3 Section number reference reads 1311.1.4, 1311.6.1, and 1311.8. Correct to read 1312.1.4, 1312.6.1, and 1312.8.
Section 1312.2.5 Section number reference reads 1311.2.4.1. Correct to read 1312.2.4.1.
Section 1312.4 Section number reference reads 1311.4.1 through 1311.4.3. Correct to read 1312.4.1 through 1312.4.3.
Section 1312.7.1(6) Section number reference reads 1311.7.1. Correct to read 1312.7.1.
Section 1312.16(A) Section number reference reads 1311.13. Correct to read 1312.13.