

Errata for 2009 Uniform Mechanical Code – 1st Printing

The following is a list of changes that we found after the first printing of the 2009 Uniform Mechanical Code. These changes may or may not apply to your codebook. However, we do encourage you to check your codebook with this list to ensure that all the changes are updated. Thank you.

Chapter 3

Section 304.1.2: Redundant text. Delete “unless other means acceptable to the roof,” 04.24.09

Chapter 11

Section 1106.4: Section number reference reads 309.0. Correct to read 308.0.

Section 1106.13: Section number reference reads 310.0. Correct to read 309.0. 08.05.09

Section 1121.1: Abbreviation reads PEL. Correct to read OEL. 03.24.09

Chapter 13

Section 1312.6.3 Section number reference reads 1312.7. Correct to read 1313.7. 08.05.09