

Errata for 2009 Uniform Swimming Pool, Spa, and Hot Tub Code 1st Printing

The following is a list of changes that we found after the first printing of the 2009 Uniform Swimming Pool, Spa, and Hot Tub Code. These changes may or may not apply to your code book. However, we do encourage you to check your code book with this list to ensure that all the changes are updated. Thank you.

Chapter 3

Section 309.4 Paragraph references standard ASME A112.19.8. Correct to read “APSP 16” and delete APSP 7.

Chapter 4

Section 409.2.2 Add extraction from NFPA 54:9.3.2.2(3) to Section 409.2.2.

409.2.2 Known Air Infiltration Rate Method.

Where the air infiltration rate of a structure is known, the minimum required volume shall be determined as follows [NFPA 54:9.3.2.2]:

- (1) No change
- (2) No change
- (3) For purposes of this calculation, an infiltration rate greater than 0.60 ACH shall not be used in the equations. [NFPA 54:9.3.2.2(3)]

Section 412.7.4.3: Paragraph references Section 412.10.14.2. Correct to read Section 412.7.4.5.

Section 413.1.10: The first sentence references Table 4-7 through 4-11. Revise 4-11 to read “4-10”. The last sentence references Table 4-9 in combination with Table 4-12. Revise 4-9 to read “4-8” and 4-12 to read “4-11”.

(4) Refers to Table 4-9, revise to read “4-8”.

(6) Refers to Table 4-12, revise to read “4-11”.

Section 413.2.19 The first sentence references Tables 4-13 and 4-14. Revise 4-13 to read “4-7” and 4-14 to read “4-10”.

Chapter 5

Section 511.14.1: Text inadvertently left out. Insert text “(See Section 511.12)” at the end of the paragraph.

Table 5-38: In the Plastic Tubing Size Column it references $\frac{3}{4}$, revise to read “1”.

Chapter 6

Table 6-1 Revise Standards table to delete ASME A112.19.8-2007 and add APSP 16-2011.